

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/16/2020

Submitted Date:

11/16/2020

Document Number:

699501916

**FIELD INSPECTION FORM**

Loc ID 333225 Inspector Name: MEDINA, JUSTIN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

- 14 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccenforcement@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
, KPK		cogcc@kpk.com	All Inspections
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239679	WELL	PR	07/01/2019	OW	123-07467	CAMENISCH 1	PR

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	spill near separator see pic 2,3,4,5,6,7,8		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.	Date:	11/17/2020
Type	OTHER		
Comment:	Berms around water, and oil tank are inadequate see pic 10		
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).	Date:	12/16/2020
Type	OTHER		
Comment:	Spill site needs remediation see pic 2,3,4,5,6,7,8		
Corrective Action:	" Contact COGCC EPS staff regarding Rule 906.c."	Date:	11/17/2020
Type	OTHER		
Comment:	Internal review of COGCC data showed there was no spill report for this site.		
Corrective Action:	Remove free fluids and contact COGCC EPS staff per Rule 906.b.	Date:	11/17/2020
Type	OTHER		
Comment:	Stockpile of what appears to be contaminated soil by separator with no BMP see pic 2,3		
Corrective Action:	All stockpiled soils shall be protected from degradation due to contamination, compaction, wind and water erosion during drilling and production operations. Comply with 1002.c	Date:	11/26/2020
Type	OTHER		
Comment:	Mechanical issue by separator, and back of oil tank see pic 2,3,4,5,6,7,8,9		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	12/16/2020
Type	OTHER		
Comment:	Inaccurate location sign posted at tank see pic 10		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	12/16/2020

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	4' barb wire around tanks, Separator/ECD, Green AG fencing around gas meter run.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electric / automation		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV FIBERGLASS		,
Comment:	70 BBL				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:				Date:	
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**Facility ID: 239679 Type: WELL API Number: 123-07467 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary  On 11/16/20 at approximately 1330 I, Inspector Justin Medina conducted an on-site inspection at:  Well Name- Camenisch 1  Company Name- KPK  API- 05-123-07467  In Weld County Colorado.  While there, I observed Producing well  During this inspection the following possible compliance issues were observed:  Mechanical issue by separator, and back of oil tank see pic 2,3,4,5,6,7,8,9  Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 12/16/20  spill near separator see pic 2,3,4,5,6,7,8  Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. 11/17/20  Internal review of COGCC data showed there was no spill report for this site.  Remove free fluids and contact COGCC EPS staff per Rule 906.b. 11/17/20  Spill site needs remediation see pic 2,3,4,5,6,7,8  Contact COGCC EPS staff regarding Rule 906.c." 11/17/20  Berms around water, and oil tank are inadequate see pic 10  Repair or install berms or other secondary containment devices per Rule 906.d.(1). 12/16/20  Inaccurate location sign posted at tank see pic 10  Install sign to comply with Rule 210.d. 12/16/20  Stockpile of what appears to be contaminated soil by separator with no BMP see pic 2,3  All stockpiled soils shall be protected from degradation due to contamination, compaction, wind and water erosion during drilling and production operations. Comply with 1002.c 11/26/20</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  At time of inspection weather conditions were sunny, and calm.</p> <p>This is a summary of inspection report.</p>	medinaj	11/16/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402533699	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5292055">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5292055</a>
699501917	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5292054">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5292054</a>