

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2020

Submitted Date:

11/23/2020

Document Number:

696202043**FIELD INSPECTION FORM**Loc ID 412922 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10515Name of Operator: GUNNISON ENERGY LLCAddress: 1801 BROADWAY #1150City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		tyson.johnston@oxbow.com	
		heather.lang@oxbow.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412922	LOCATION	AC			-	DGU Federal 1289 17-11 Pad	RI

General Comment:

On 11/19/2020, Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at Gunnison Energy LLCs DGU Federal 1289 17-11 Pad location in Gunnison County, Colorado.

The following compliance issues were observed during this inspection:
§34-60-121(1)(a), C.R.S.: Form 4 condition requirements- Signage

Refer to the "Location" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	<p>Pursuant to conditions within the 502.b Delayed Interim Reclamation NTO document #401463219, Operator was required to post a sign at the location entrance stating the following: "A COGCC variance has been approved to delay the commencement of interim reclamation to no later than December 9, 2022".</p> <p>It was observed in this inspection that signage with required information has not been installed at the Location entrance in a plainly visible manner, in accordance with Form 4 conditions.</p>		
Corrective Action:	Comply with Form 4 #401463219 and post a sign at the location entrance stating the following: " A COGCC variance has been approved to delay the commencement of interim reclamation to no later than December 9, 2022". A CA date of 3/15/2019 is being provided as this was when the sundry variance and conditions were approved.	Date:	03/15/2019

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 412922 Type: LOCATION API Number: - Status: AC Insp. Status: RI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696202044	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5296311