

Inspection Photos

11/19/2020

Operator: SG INTERESTS I LTD # 77330

Location ID: 422990

Gunnison, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 414132



Photos taken from doc. #696201335. Photos show overview of the Location and current pad. Delayed IR variance doc. #401721595 expired, and required interim reclamation pursuant to 1003 rules no later than February 5th, 2020. Interim reclamation of areas not needed for production has not been conducted per 1003 rules, and Form 4 COAs.

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 422990



Photo 1: Photo taken from the stormwater ditch on the west end of the Location. Operator has installed a sediment trap. BMP insufficient in size for the site's conditions and have not been installed in accordance with good engineering practices.

Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 422990



Photo 3: Photo taken from the stormwater ditch on the west end of the Location, facing north. Photo shows ditch BMP has not been constructed in accordance with good engineering per the sites conditions.



Photo 4: Photo taken from the stormwater ditch. Photo shows straw wattle as a velocity check in the ditch.

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 422990



Photo 5: Photo taken from the west end of the Location, facing south east. Photo shows example of slopes on the Location where stabilization BMPs remain missing or insufficient.



Photo 6: See comments under photo 5.