

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2020

Submitted Date:

11/23/2020

Document Number:

693802532**FIELD INSPECTION FORM**Loc ID 322103 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10754Name of Operator: FOUR CORNERS ENERGY LLCAddress: 531 E 770 NCity: OREM State: UT Zip: 84097**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 11 Number of Comments
- 2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Rabinowitz, Daniel	970-385-1363	drabinow@blm.gov	<a href="#">Durango</a>
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	<a href="#">Field Inspector</a>
Pesicka, Conor		conor.pesicka@state.co.us	
Williams, Larry	(801) 657-5780	larry@thesummitcompanies.com	
Telecky, Barbara		btelecky@blm.gov	<a href="#">Durango</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208971	WELL	SI	10/01/2017	GW	033-06076	HUGUS FEDERAL 1	TA

**General Comment:**

COGCC staff performed a followup field inspection on 11/17/2020. Followup to inspection doc#693802464 on 10/4/2020. Issues were found requiring corrective action. CAs from previous inspection not completed. See inspection text and photos for details. Any Corrective Actions from previous inspections that have not been addressed are still applicable.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Dirt and gravel access road.		
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/14/2020
Type	WELLHEAD		
Comment:	Operator information updated. CA completed		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	CA completed 801-657-5780 or 435-279-7144		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	CA completed.		
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>				corrective date
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:		Date:		
Type: Bradenhead	# 1			
Comment:				
Corrective Action:		Date:		
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:		Date:		

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

CRUDE OIL	1	400 BBLs	STEEL AST		37.649192,-108.972403	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	400 BBLs	STEEL AST		37.649192,-108.972403	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Both tanks inside same berms.				
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 208971 Type: WELL API Number: 033-06076 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well shut in 4/2016. No MIT on record.  
Well was found in state of Temporary Abandonment. Well TA longer than 6 months with no Form 4 submitted  
Well is overdue for Mechanical Integrity Test (MIT). MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well.  
Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b.

Corrective Action: Submit Form 4 as directed by Rule 319.b  
Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 326 and 208.

Date: 11/03/2020

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693802546	Inspection photos 11/19/2020	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5297926">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5297926</a>