

Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #1 tank battery from access road, looking Northeast



Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #2 Tank Battery looking east



Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #2 tank battery from pad of IJ well, Dwinell #2.



Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #4 AGT tank and flowline riser

Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #5 inside Tank battery, open excavation. Sandy soil observed.

Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #6 back of south western most tank.

Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #7 area in grey is the spill point for spill 478606. Crew was on location at the time of inspection attempting to remove fluid from a valve near the failed part of tank (low on tank). The tank was reported as mostly empty by pumper, that statement appeared consistent with observations.



Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #8 AGT, looking east. These four tanks are on the north side of the tank battery.

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #9 AGT, looking east. These four tanks are on the north side of the tank battery.

Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #10 North most tanks. Pumpbuilding on left of photo.

Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #11 Pump building on right, looking west.

Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #12 ground around tanks near pumpbuilding.

Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #13 treaters.

Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #14 near treater, debris and weeds

Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #15 treater battery, debris and trash

Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #16 pit facility 115239.

Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #17 pit facility 115239.



Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #18 Fire line that was constructed east of pit 115239



Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #19 Injection well at left of photo, soils have been disturbed to the east of wellhead and east of pit facility 115239.



Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #20 Historic aerials show a pit at this location. The pit appears to have been backfilled. Provide demonstration of compliance with table 910-1 on a Form 27 for this pit. (40.822076,-106.232522 is approx center of pit)



Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #21 Historic aerials show a pit at this location. The pit appears to have been backfilled. Provide demonstration of compliance with table 910-1 on a Form 27 for this pit. (40.822076,-106.232522 is approx center of pit)



Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #22 Trash on pad near old pit described in Photo #21



Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #23 Trash on pad near old pit described in Photo #24

Inspection Photos

Remediation Project 15326

Location 465486

Spill 473059

Well 057-05129

Inspection Date: 11/20/2020

All Photos taken by Kris Neidel



Photo #24 Historic aerials show a pit at this location. The pit appears to have been backfilled. Provide demonstration of compliance with table 910-1 on a Form 27 for this pit. (40.822076,-106.232522 is approx center of pit)

