

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402547508

Date Received:  
12/07/2020

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

0 CA Completed  
3 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 34105  
Name of Operator: GILBERT-STEWART OPERATING LLC  
Address: 1801 BROADWAY STE 200  
City: DENVER State: CO Zip: 80202  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Muniz, Gentry</u>		<u>Gentry.Muniz@WSP.com</u>
<u>GILBERT, KENT</u>	<u>303-534-1686</u>	<u>kgoil@msn.com</u>
<u>Kasola, Jason</u>		<u>jason.Kasola@state.co.us</u>
<u>Roy, Chris</u>		<u>Chris.Roy@WSP.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 700600223  
Inspection Date: 12/01/2020 FIR Submit Date: 12/02/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: GILBERT-STEWART OPERATING LLC Company Number: 34105  
Address: 1801 BROADWAY STE 200  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 475565

Location Name: YELTSIN-615S45W Number: 1SWSE County: \_\_\_\_\_  
Qtrqr: SESE Sec: 1 Twp: 15S Range: 45W Meridian: 6  
Latitude: 38.770553 Longitude: -102.390873

FACILITY - API Number: 05-017-00 Facility ID: 475565

Facility Name: YELTSIN-615S45W Number: 1SWSE  
Qtrqr: SESE Sec: 1 Twp: 15S Range: 45W Meridian: 6  
Latitude: 38.770553 Longitude: -102.390873

CORRECTIVE ACTIONS:

1 CA# 144778

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).

Date: 12/22/2020

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: The Akers #2 Well is a TA Well. Gilbert-Stewart Operating is in the process of disconnecting tanks and FWKO cleaning them and locating them in the Yeltsin yard ( to the west of the Akers #2 Lease).No berms or containment are needed at this time, therefore compliance with Rule 906.d(1) is not pertinent at this time.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**2** CA# 144779

Corrective Action: Comply with Rule 603.f .

Date: 12/09/2020

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: Gilbert-Stewart Operating will comply with Rule 603.f as to the removal of the pieces of plastic liner. Due to sampling and weather Gilbert-Stewart respectfully requests until 1/22/21 to comply with this request.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**3** CA# 144780

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.

Date: 01/02/2021

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: Gilbert-Stewart Operating is in the process of cleaning up the Akers #2 Tank Battery as the well is TA. The stained soil around the Tank Battery will be sampled by WSP (formerly LT Environmental) to make a basis of determination of the disposition of the soil per Rule 906.a Due to weather and extenuating circumstances Gilbert-Stewart Operating respectfully requests that the cleanup completion date be 1/22/21.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kent Gilbert

Signed: \_\_\_\_\_

Title: Manager

Date: 12/7/2020 10:06:08 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

Total Attach: 0 Files