

TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 29NWNE
Location ID: 311561



**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 29NWNE
Location ID: 311561**



GM 331-29 well sign is not installed.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 29NWNE
Location ID: 311561**



**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 29NWNE
Location ID: 311561**



Ruts around separators and tank battery.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 29NWNE
Location ID: 311561**



Ruts around wells

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 29NWNE
Location ID: 311561**



**No BMPs around well head CHEVRON #
MV-35-29.**

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 29NWNE
Location ID: 311561**



Loaction looks to have expanded.

Ditch along road running through location has dirt pile blocking flow.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 29NWNE
Location ID: 311561**



Equipment and materials stored on location.



Equipment and materials stored on location.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 29NWNE
Location ID: 311561**



Unmarked deadman.



Unmarked deadman.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 29NWNE
Location ID: 311561**



**Ditch behind tank battery and separators
has sediment build up.**

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 29NWNE
Location ID: 311561**



Checkdam behind tank battery is washed out and needs maintained.