

ARGENTA 34-10 31-1

Corrective Actions Taken on the ARGENTA 34-10 31-1 for the COGCC
INC.

Seeded and Mulched to stabilized disturbed soil near the well pad entrance.





Seeded and mulched location access road due vehicle tracking disturbance.





