



Corrective Actions Report

API#: 057-06625

Site Name: Eagle Hill 1-32

Operator: Gulf Exploration

Correction End Date: 12/11/20

Prepared by: Justin Keith



Picture 1 & 2: Contractor tried several operations to alleviate soil compaction but with the frost in the soil this proved to create large clumps and ultimately an improper seed bed.




Picture 3: With seeding operations not possible at this time, we needed to properly stabilize the soil. All areas with vertical ripping marks were cross ripped with a dozer on the contour and then tracked in to break up large clumps and help hold the soil in place.



Picture 4 & 5: Erosion Logs were moved and properly installed per product specifications.



Picture 6: Swale area cross ripped and tracked in with dozer. Erosion logs removed from the swale and added to the side hills to prevent erosion.



Pictures 7 & 8: TRM mat that will handle any spring flows through the swale was installed after contractor reworked swale to insure proper drainage.

Note: Products were installed the day previous before snow, but darkness didn't allow for proper pictures.