

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402560783

Date Received:

12/28/2020

Spill report taken by:

Hughes, Jim

Spill/Release Point ID:

478512

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>SIMCOE LLC</u>	Operator No: <u>10749</u>	Phone Numbers
Address: <u>THREE ALLEN CENTER, 333 CLAY ST SUITE 3900</u>		Phone: <u>(505) 330-9179</u>
City: <u>HOUSTON</u>	State: <u>TX</u>	Zip: <u>77002</u>
Contact Person: <u>Steve Moskal</u>		Mobile: <u>(505) 330-9179</u>
		Email: <u>smoskal@ikavenergy.com</u>

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 402527600

Initial Report Date: 11/07/2020 Date of Discovery: 11/06/2020 Spill Type: Recent Spill

Spill/Release Point Location:

QTRQTR NENW SEC 30 TWP 33N RNG 7W MERIDIAN N

Latitude: 37.080441 Longitude: -107.654247

Municipality (if within municipal boundaries): _____ County: LA PLATA

Reference Location:

Facility Type: FLOWLINE SYSTEM Facility/Location ID No 215421

Spill/Release Point Name: Simms E 1 Well API No. (Only if the reference facility is well) 05- -

No Existing Facility or Location ID No.

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): >=100

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: Approximately 245 bbls of produced water on pad, with minimal leaving edge of well pad

Land Use:

Current Land Use: NON-CROP LAND Other(Specify): Well Pad

Weather Condition: Clear, 70F

Surface Owner: FEE Other(Specify): Private

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State Residence/Occupied Structure Livestock Public Byway Surface Water Supply Area

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

Produced water release from underground flowline, flowed accross pad to rock rundown, where operators stopped the release with a small berm.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
11/7/2020	Landowner	Private	--	BP Land negotiator to contact landowner
11/6/2020	COGCC	Jim Hughes	970-903-4072	Left Voicemail
11/7/2020	La Plata Co	Shawna Legarza	---	Email with response
11/6/2020	SUIT	Doug Krueger	970-769-3017	Left voicemail as a courtesy notification

Was there a Grade 1 Gas Leak? Yes No

If YES, enter the Document Number of the Grade 1 Gas Leak Report Form 44: _____

Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? Yes No

If YES, enter the Document Number of the Initial Accident Report, Form 22: _____

Was there damage during excavation? Yes No

If YES, was CO 811 notified prior to excavation? Yes No

CORRECTIVE ACTIONS

#1 Supplemental Report Date: 12/28/2020

Root Cause of Spill/Release Pipe, Weld, or Joint Failure

Other (specify) _____

Type of Equipment at Point of Spill/Release: Horizontal Heated Separator

If "Other" selected above, specify or describe here:

Describe Incident & Root Cause (include specific equipment and point of failure)

1" nipple on separator failed due to physical stress, resulting in release.

Describe measures taken to prevent the problem(s) from reoccurring:

Piping was replaced and corrected alignment to reduce stress.

Volume of Soil Excavated (cubic yards): 0

Disposition of Excavated Soil (attach documentation) Offsite Disposal Onsite Treatment

Other (specify) _____

Volume of Impacted Ground Water Removed (bbls): 0

Volume of Impacted Surface Water Removed (bbls): 0

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: Corrective Actions Completed (documentation attached)

Work proceeding under an approved Form 27

Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

SS06 (24-28") was collected near SS03 (0-6"), and indicated a reduction in SAR from 16.5 to 2.18 and a reduction in conductivity from 3.780 mmhos/cm to 0.550 mmhos/cm.

SS05 (24-28") was collected near SS01 (0-6"), and indicated a reduction in SAR from 12.0 to 1.30 and a reduction in conductivity from 2.120 mmhos/cm to 0.995 mmhos/cm.

All impacts remain on pad and demonstrate no need for further remedial action.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Steve Moskal

Title: Enviro Coord Date: 12/28/2020 Email: smoskal@ikavenergy.com

COA Type

Description

	As stated in the response to FAQ #31, "an operator need not meet a concentration level specified in Table 910-1 if the operator can demonstrate to the COGCC's satisfaction that the Table 910-1 level is exceeded by the background level in the native soils or ground water, as applicable." The operator shall provide background concentration levels to demonstrate native exceedances of Table 910-1 along with a formal request for relief from the elevated contaminants of concerns. The operator shall then be required to meet the concentration levels determined to exist in the native soil/groundwater, with prior approval by the COGCC. The operator has not provided documentation that successfully demonstrates results from impacted areas are similar to native soil Arsenic values. During final reclamation the operator shall ensure compliance with Table 910-1 clean up standards.
	Based on review of the information provided, it appears that no further action is necessary at this time and COGCC approves the closure request. Should conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards, or, if groundwater is found to be significantly impacted, further investigation and/or remediation activities may be required at the site.

Attachment List

<u>Att Doc Num</u>	<u>Name</u>
402560783	SPILL/RELEASE REPORT(SUPPLEMENTAL)
402560795	ANALYTICAL RESULTS
402560798	ANALYTICAL RESULTS
402560800	SITE MAP
402560802	OTHER
402560804	ANALYTICAL RESULTS
402560805	ANALYTICAL RESULTS
402561509	FORM 19 SUBMITTED

Total Attach: 8 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)