

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWE
Location # 335654**



**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWNE
Location # 335654**



Sediment build up inside of tracking cattle guard style tracking pad.



Sediment build up inside of tracking cattle guard style tracking pad.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWE
Location # 335654**



Culvert at intersection before the bottom guard shack has waddle that's damaged and sediment in ditch/culvert outlet



Culvert at intersection before the bottom guard shack has waddle that's damaged and sediment in ditch/culvert outlet