

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402530557

Date Received:

11/11/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10524

Name of Operator: GRMR OIL & GAS LLC

Address: P.O. BOX 6280

City: BROOMFIELD State: CO Zip: 80021

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Joe Harrick</u>	<u>724-935-9815</u>	<u>jharrick@jklmenergy.com</u>
<u>Stephanie Tubridy</u>	<u>724-935-9812</u>	<u>stubridy@jklmenergy.com</u>
<u>John Leone</u>	<u>970-824-6827</u>	<u>John.Leone@grmroilandgas.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 692402482

Inspection Date: 08/27/2020

FIR Submit Date: 09/01/2020

FIR Status: _____

Inspected Operator Information:

Company Name: GRMR OIL & GAS LLC

Company Number: 10524

Address: P.O. BOX 6280

City: BROOMFIELD State: CO Zip: 80021

LOCATION - Location ID: 418843

Location Name: Durham Number: 1-31, 2-31 County: _____

Qtrqtr: SWSE Sec: 31 Twp: 5N Range: 90W Meridian: 6

Latitude: 40.335485 Longitude: -107.534252

FACILITY - API Number: 05-081-00 Facility ID: 418843

Facility Name: Durham Number: 1-31, 2-31

Qtrqtr: SWSE Sec: 31 Twp: 5N Range: 90W Meridian: 6

Latitude: 40.335485 Longitude: -107.534252

CORRECTIVE ACTIONS:

1 ☒ CA# 141645

Corrective Action: Perform final reclamation on the access road and location per COGCC 1004 Rules including but not limited to recontouring, replacement of topsoil, and seeding of site. Install and maintain appropriate BMPs to stabilize location until uniform vegetation establishes across all disturbance areas. All reclamation activities to be complete by 11/16/20.

Date: 11/16/2020

Response: CA COMPLETED

Date of Completion: 10/23/2020

Operator: Weeds sprayed on 09/21/2020
Comment: Eroision an BMP's repaired on 09/28/2020
Surface owner variance request submitted on 10/23/2020

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 141646

Corrective Action: Install or repair required BMPs per Rule 1002.f in conjunction with reclamation activities at the site. Maintain BMPs for stabilization of location until uniform vegetation is established across all disturbance areas.

Date: 11/16/2020

Response: CA COMPLETED

Date of Completion: 10/23/2020

Operator: Weeds sprayed on 09/21/2020
Comment: Erosion and BMP's repaired on 09/28/2020
Surface owner variance request submitted on 10/23/2020

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Joseph M. Harrick

Signed: _____

Title: General Manager EHS

Date: 11/11/2020 12:00:45 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402530557	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files