

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402574275

Date Received:

01/13/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

MacLaren, Joe

joe.maclaren@state.co.us

Knop, Max

303-825-4822

MKnop@kpk.com

Inspections, KPK

cogcc@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697601156

Inspection Date: 01/06/2021

FIR Submit Date: 01/08/2021

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 332971

Location Name: HLADKY-O'GORMAN-62N66W Number: 21NWSW County: _____

Qtrqtr: NWS Sec: 21 Twp: 2N Range: 66W Meridian: 6
W

Latitude: 40.121440 Longitude: -104.789870

FACILITY - API Number: 05-123- -00 Facility ID: 476187

Facility Name: Wellhead Line Number: 21NWSW

Qtrqtr: NWS Sec: 21 Twp: 2N Range: 66W Meridian: 6
W

Latitude: 40.121440 Longitude: -104.789870

CORRECTIVE ACTIONS:

1 CA# 145762

Corrective Action:

Date: 01/15/2021

Provide chronology and brief description of operator's actions with respect to report of spill/release related to this flowline (from complainant or family members) including dates, times and results of any flowline integrity investigations performed on this flowline in the the two years previous to today (9 January 2019 to 8 January 2021).

If operator has not successfully pressure tested the flowline between the well production facilities since being notified by the complainant of the possible spill/release the a pressure test must be performed in response and as investigation of spill/release that threatened or harmed soil and vegetation.

Contact COGCC engineering integrity Inspector with schedule of any pressure testing to be done in response to this report with a minimum of 48 hour notice.. Provide pressure testing charts for this active flowline at this site; email to COGCC Inspector (See rule 1102.O).

Response: CA COMPLETED

Date of Completion: 01/13/2021

Operator Comment: KPK performed integrity tests of associated well flowline and facility dump lines on October 2, 2020 in response to complaint. Test results showed not integrity issues. Based on the results of the performed pressure tests, KPK has concluded its investigation.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Max Knop

Signed: _____

Title: Gen Mangr of Air Quality

Date: 1/13/2021 4:34:44 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402574278	Pressure Test
-----------	---------------

Total Attach: 1 Files