

TEP ROCKY MOUNTAIN LLC
PA-66S95W 33SWSW
Location # 334970



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present)**

**TEP ROCKY MOUNTAIN LLC
PA-66S95W 33SWSW
Location # 334970**



**Road shows signs of lack of stabilization
BMP's in some areas (rutting is present)**

**TEP ROCKY MOUNTAIN LLC
PA-66S95W 33SWSW
Location # 334970**



**Road shows signs of lack of stabilization
BMP's in some areas (rutting is present)**