

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402571499

Date Received:
01/11/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Mack, Ronald</u>	<u>719-859-4896</u>	<u>rmack@ogrisop.com</u>
<u>Santistevan, Vince</u>	<u>719-845-2102/719-680-9705</u>	<u>vincesantistevan@tcenergyllc.com</u>
<u>Fitzgerald, Edie</u>	<u>719-859-1394</u>	<u>efitzgerald@ogrisop.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 700600149
Inspection Date: 09/12/2020 FIR Submit Date: 09/15/2020 FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309175

Location Name: GOLDEN EAGLE-633S67W Number: 30SWNW County: LAS ANIMAS
Qtrqtr: SWN Sec: 30 Twp: 33S Range: 67W Meridian: 6
W
Latitude: 37.145232 Longitude: -104.934732

FACILITY - API Number: 05-071-00 Facility ID: 289504

Facility Name: GOLDEN EAGLE Number: 30-05
Qtrqtr: SWN Sec: 30 Twp: 33S Range: 67W Meridian: 6
W
Latitude: 37.145232 Longitude: -104.934732

CORRECTIVE ACTIONS:

1 CA# 142007

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 09/30/2020

Response: CA COMPLETED

Date of Completion: 01/06/2021

Operator Comment: THE LEAK ON THE COMPRESSOR WAS REPAIRED. ALL FITTINGS ARE SECURLY FASTENED. THE FLUID ACCUMULATION WAS REMOVED FROM THE CONTAINMENT. THE IMPACTED SOIL NEAR THE LIQUID RING COMPRESSOR WAS REMOVED. SEE ATTACHED PHOTO LOG FOR DETAILS.

COGCC Decision: Approved via an AMI

COGCC Representative: Attached photos show location has been cleaned up per corrective action.

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald Signed: _____
Title: Sr. Environmental Tech. Date: 1/11/2021 11:32:03 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402571499	FIR RESOLUTION SUBMITTED
402571514	Photo Log

Total Attach: 2 Files