

BERRY PETROLEUM COMPANY LLC
CHEVRON L04 696
Location # 335597



BERRY PETROLEUM COMPANY LLC
CHEVRON L04 696
Location # 335597



BERRY PETROLEUM COMPANY LLC
CHEVRON L04 696
Location # 335597



No evidence of tracking control BMP's



No evidence of tracking control BMP's

BERRY PETROLEUM COMPANY LLC
CHEVRON L04 696
Location # 335597



N39.55098 W-108.12060



Sediment blockage in ditch.

BERRY PETROLEUM COMPANY LLC
CHEVRON L04 696
Location # 335597



N39.55348 W-108.11985



Water not draining off road.

BERRY PETROLEUM COMPANY LLC
CHEVRON L04 696
Location # 335597



Sediment build up in culvert outlet.



Erosion damage from culvert outlet.

BERRY PETROLEUM COMPANY LLC
CHEVRON L04 696
Location # 335597



Erosion damage from culvert outlet.



Erosion damage from culvert outlet.