

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402551010

Date Received:  
12/10/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Beebe, Sabre</u>	<u>970-769-9523</u>	<u>sabre.beebe@ikavenergy.com</u>
<u>Beebe, Sabre</u>		<u>sabre.beebe@bpx.com</u>
		<u>SanJuanCOGCC@bp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900193  
Inspection Date: 04/09/2019 FIR Submit Date: 04/16/2019 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 325081

Location Name: WILDE GAS UNIT-N33N7W Number: 31NWSE County: LA PLATA  
Qtrqtr: NWSE Sec: 31 Twp: 33N Range: 7W Meridian: N  
Latitude: 37.058110 Longitude: -107.646707

FACILITY - API Number: 05-067-00 Facility ID: 213951

Facility Name: WILDE Number: 1  
Qtrqtr: NWSE Sec: 31 Twp: 33N Range: 7W Meridian: N  
Latitude: 37.058110 Longitude: -107.646707

CORRECTIVE ACTIONS:

1  CA# 124331

Corrective Action: Reclamation is needed around wellhead marker, in former facilities area, and access road. Areas need to be reclaimed to COGCC final reclamation rules including removal of gravel, culvert, decompaction to 18 inches and revegetation. Weeds need to be monitored and controlled.

Date: 05/17/2019

Response: CA COMPLETED Date of Completion: 12/02/2020

Reclamation work completed. Culvert per landowner is not BP property but is his property and must remain in

Operator Comment: the ditch for irrigation water flow.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2  CA# 124332

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the southern project area. Temporary stormwater and erosion controls will be needed until long term stabilization is achieved.

Date: 05/17/2019

Response: CA COMPLETED

Date of Completion: 12/02/2020

Operator Comment: work completed for a second time

COGCC Decision: Approved pending re-inspection

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Consultation with the surface owner uncovered that the culvert belongs to him and must remain in the ditch for flow of his irrigation water. Reclamation area has been reworked. Seeding and mulching had been performed a second time see attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Specialist

Date: 12/10/2020 11:33:37 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402551010	FIR RESOLUTION SUBMITTED
402551018	work completion photos

Total Attach: 2 Files