

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402365284

Date Received:

04/08/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10691

Name of Operator: PHOENIX RESOURCES LLC

Address: 5566 S SYCAMORE STREET

City: LITTLETON State: CO Zip: 80120

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Heffner, Taylor

303-219-3362

theffner@phxresources.com

Eisenach, Jason

970-301-0499

jeisenach@phxresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688307521

Inspection Date: 03/30/2020

FIR Submit Date: 03/30/2020

FIR Status: _____

Inspected Operator Information:

Company Name: PHOENIX RESOURCES LLC

Company Number: 10691

Address: 5566 S SYCAMORE STREET

City: LITTLETON State: CO Zip: 80120

LOCATION - Location ID: 317095

Location Name: ATKINSON-CHENOWETH-63S56W Number: 30NENE County: WASHINGTON

Qtrqtr: NENE Sec: 30 Twp: 3S Range: 56W Meridian: 6

Latitude: 39.767350 Longitude: -103.689500

FACILITY - API Number: 05-121-00 Facility ID: 236181

Facility Name: ATKINSON-CHENOWETH Number: 4

Qtrqtr: NENE Sec: 30 Twp: 3S Range: 56W Meridian: 6

Latitude: 39.767350 Longitude: -103.689500

CORRECTIVE ACTIONS:

1 ☒ CA# 137571

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).

Date: 03/06/2020

Response: CA COMPLETED

Date of Completion: 04/02/2020

Operator
Comment:

All holes found in the berms surrounding the location have been filled and graded. Photos attached.

There was some miscommunication/confusion internally regarding the previous FIR Resolution we filed for this location - the berm work performed at that time was for the CHM 1-A (05-123-08843). All photos attached to this FIRR reflect the Atkinson-Chenoweth location.

COGCC Decision: Approved via an AMI

COGCC
Representative:

2 ☒ CA# 137572

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d and properly dispose of E&P stained soil.

Date: 04/17/2020

Response: CA COMPLETED

Date of Completion: 04/02/2020

Operator Comment: Stuffing box rubbers have been replaced at the wellhead and all stained soil has been cleaned up and disposed of - picture attached.

COGCC Decision: Approved via an AMI

COGCC
Representative:

3 ☒ CA# 137573

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).

Date: 04/17/2020

Response: CA COMPLETED

Date of Completion: 04/02/2020

Operator Comment: All holes found in the berms surrounding the location have been filled and graded. Photos attached.
There was some miscommunication/confusion internally regarding the previous FIR Resolution we filed for this location - the berm work performed at that time was for the CHM 1-A (05-123-08843). All photos attached to this FIRR reflect the Atkinson-Chenoweth location.

COGCC Decision: Approved via an AMI

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Taylor Heffner

Signed: _____

Title: Partner

Date: 4/8/2020 1:16:27 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402365284	FIR RESOLUTION SUBMITTED
402365309	Atkinson-Chenoweth 4 Inspection Follow-Up Photos

Total Attach: 2 Files