



Well Name:	RGU 343-1-298	Prepared By:	Richard Miller
Location:	SESE 1 2S-98W 6 PM	Office Phone:	832-726-1173
County:	Rio Blanco	Date:	2/1/2021
Field:	Sulphur Creek	API:	05-103-11027

Surface Casing: 9-5/8", 36.0 ppf, J-55 @ 3,098'

Production Casing: 4-1/2", 11.60 ppf, I-110 @ 12,001'

TOC: 2,150'

Tubing: 2-3/8", 4.70 ppf, L-80 @ 11,442'

Perforations: 9,076' – 11,669'

Purpose: Find and repair leak in production casing

Proposed Procedure:

1. MIRU service unit, kill well.
2. NU BOP and test.
3. POOH 2-3/8" tubing.
4. RIH with 4-1/2" TSBP.
5. Set BP at $\pm 5,720'$.
6. Pull casing slips and lay down parted casing.
7. Manually backoff production casing below joint with leak.
8. POOH with casing and lay down.
9. RIH with new casing and screw back into existing casing.
10. Pressure test casing.
11. RIH and retrieve RBP. POOH.
12. RIH with production tubing. Land tubing at 11,442'.
13. RDMO service unit.