

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402554076

Date Received:  
12/15/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10728

Name of Operator: GULF EXPLORATION LLC

Address: 9701 N BROADWAY EXTENSION

City: OKLAHOMA CITY State: OK Zip: 73114

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

parks.barroso@coag.gov

scott.schultz@coag.gov

sstrickland@gulfexploration.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 692402693

Inspection Date: 11/19/2020

FIR Submit Date: 12/02/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: GULF EXPLORATION LLC

Company Number: 10728

Address: 9701 N BROADWAY EXTENSION

City: OKLAHOMA CITY State: OK Zip: 73114

LOCATION - Location ID: 466705

Location Name: Eagle Hill Number: 1-32 Pad County: \_\_\_\_\_

Qtrqtr: NWNE Sec: 32 Twp: 10N Range: 78W Meridian: 6

Latitude: 40.799820 Longitude: -106.170270

FACILITY - API Number: 05-057-00 Facility ID: 466705

Facility Name: Eagle Hill Number: 1-32 Pad

Qtrqtr: NWNE Sec: 32 Twp: 10N Range: 78W Meridian: 6

Latitude: 40.799820 Longitude: -106.170270

CORRECTIVE ACTIONS:

1  CA# 144801

Corrective Action: Perform Final Reclamation per COGCC 1004 Rules. Due to enforcement actions CA Date is not given.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 12/11/2020

Operator Comment: With seeding operations not possible at this time due to frost in the soil, all areas with vertical ripping marks were cross ripped with a dozer on the contour and then tracked in to break up large clumps and help hold the soil in place. The swale area was cross ripped and tracked in with a dozer.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**2**  CA# 144802

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 08/19/2019

Response: CA COMPLETED

Date of Completion: 12/11/2020

Operator Comment: Erosion logs were moved and properly installed per product specifications. Erosion logs were removed from the swale and added to the side hills to prevent erosion. A TRM mat that will handle any spring flows through the swale was installed after contractor reworked swale to insure proper drainage.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sean Strickland

Signed: \_\_\_\_\_

Title: Operations Manager

Date: 12/15/2020 9:28:33 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
402554076	FIR RESOLUTION SUBMITTED
402554100	Corrective Actions Report

Total Attach: 2 Files