

TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 35SWSW
Location # 334773



**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 35SWSW
Location # 334773**



No capacity on tank or label.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 35SWSW
Location # 334773**



Unused equipment (polylines)



Weathered well signs

TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 35SWSW
Location # 334773




Weathered well sign



Weathered well sign



TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 35SWSW
Location # 334773



Weathered well sign



Weathered well sign

TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 35SWSW
Location # 334773



No tracking bmps observed for access road.



Storm water bmps are failing at access right away and CR215.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 35SWSW
Location # 334773**



Deadman marker broken off and not at deadman.



Unmarked deadman.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 35SWSW
Location # 334773**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 35SWSW
Location # 334773**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 35SWSW
Location # 334773**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 35SWSW
Location # 334773**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**