

**TEP ROCKY MOUNTAIN LLC  
AMERICAN SODA-66S96W 35SWSW  
Location # 324121**



**TEP ROCKY MOUNTAIN LLC  
AMERICAN SODA-66S96W 35SWSW  
Location # 324121**



**No capacity on tank or tank label.**

**TEP ROCKY MOUNTAIN LLC  
AMERICAN SODA-66S96W 35SWSW  
Location # 324121**



**Location shows signs of lack of stabilization  
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC  
AMERICAN SODA-66S96W 35SWSW  
Location # 324121**



**Location shows signs of lack of stabilization  
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC  
AMERICAN SODA-66S96W 35SWSW  
Location # 324121**



**Erosion riling down hill from location**

**TEP ROCKY MOUNTAIN LLC  
AMERICAN SODA-66S96W 35SWSW  
Location # 324121**



**Sediment build up at fork from location to main access road.**

**TEP ROCKY MOUNTAIN LLC  
AMERICAN SODA-66S96W 35SWSW  
Location # 324121**



**Ground subsidence where polyline is buried across access road.**

**TEP ROCKY MOUNTAIN LLC  
AMERICAN SODA-66S96W 35SWSW  
Location # 324121**



**Ground subsidence where polyline is buried across access road.**

**TEP ROCKY MOUNTAIN LLC  
AMERICAN SODA-66S96W 35SWSW  
Location # 324121**



**Junk fence posts and barb wire.**



**Tee post along access road.**

**TEP ROCKY MOUNTAIN LLC  
AMERICAN SODA-66S96W 35SWSW  
Location # 324121**



**Junk culvert pieces on side of access road.**