

GOLDEN EAGLE 20-03 API# 05-071-08734 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: FEBUARY 05, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200640



PHOTO 1: THE ROAD SURFACE WAS REGRADED TO CREATE SHEET FLOW AND ELIMINATE THE TIRE RUTS/
SURFACE EROSION.

GOLDEN EAGLE 20-03 API# 05-071-08734 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: FEBUARY 05, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200640



PHOTO 2: THE BAR DITCH WAS DOMINATED TO RECEIVE STORMWATER RUN OFF FROM THE ACCESS ROAD.

GOLDEN EAGLE 20-03 API# 05-071-08734 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: FEBUARY 05, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200640



PHOTO 3: THE SEDIMENT ACCUMULATION WAS REMOVED FROM THE CULVERT INLET