

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/29/2021

Submitted Date:

01/29/2021

Document Number:

699502199**FIELD INSPECTION FORM**Loc ID 323229 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244950	WELL	PR	03/20/1995	OW	123-12745	ROCKY MOUNTAIN FUEL C-10	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment: mechanical issue with gas motor / stained soil under gas motor.

Corrective Action: Comply with COGCC housekeeping rules.

Date: 03/01/2021

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bradenhead

# 1

Comment:

Corrective Action:

Date:

Type: Pump Jack

# 1

Comment:

Corrective Action:

Date:

Type: Prime Mover

# 1

Comment: gas motor

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 244950 Type: WELL API Number: 123-12745 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 02/15/2019 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0Comment: Annual Bradenhead test is not current. Contact COGCC engineering.02/08/2021Corrective Action: Comply with COGCC annual bradenhead testing rules.

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 1/29/21 at approximately 1200 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Rocky Mountain Fuel C-10</p> <p>Company Name- KPK</p> <p>API- 05-123-12745</p> <p>In Weld County Colorado.</p> <p>While there, I observed PR well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Mechanical issue with gas motor / stained soil.</p> <p>Comply with COGCC housekeeping rules 3/1/21</p> <p>Annual Bradenhead test is not current. Contact COGCC engineering.</p> <p>Comply with COGCC annual bradenhead testing rules. 2/8/21</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	01/29/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402587182	INSPECTION SUBMITTED	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5340866">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5340866</a>
699502200	pics	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5340853">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5340853</a>