

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402590480

Date Received:
02/03/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10091
Name of Operator: BERRY PETROLEUM COMPANY LLC
Address: 11117 RIVER RUN BLVD
City: BAKERSFIELD State: CA Zip: 93311

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Armstrong, Jon</u>		<u>jarmstrong@bry.com</u>
<u>Kellerby, Shaun</u>		<u>shaun.kellerby@state.co.us</u>
<u>Wilbourn, Don</u>		<u>dwilbourn@bry.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 701101080
Inspection Date: 01/22/2021 FIR Submit Date: 01/22/2021 FIR Status: _____

Inspected Operator Information:

Company Name: BERRY PETROLEUM COMPANY LLC Company Number: 10091
Address: 5201 TRUXTUN AVENUE #100
City: BAKERSFIELD State: CA Zip: 90339

LOCATION - Location ID: 335658

Location Name: CHEVRON Number: 036B 596 County: _____
Qtrqtr: SWSE Sec: 36 Twp: 5S Range: 96W Meridian: 6
Latitude: 39.567198 Longitude: -108.114538

FACILITY - API Number: 05-045-00 Facility ID: 335658

Facility Name: CHEVRON Number: 036B 596
Qtrqtr: SWSE Sec: 36 Twp: 5S Range: 96W Meridian: 6
Latitude: 39.567198 Longitude: -108.114538

CORRECTIVE ACTIONS:

1 CA# 146066

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C
Install, maintain or provide documentation of post construction management plan or
BMP??s.

Date: 02/06/2021

Response: CA COMPLETED Date of Completion: 02/02/2021

Cleaned sediment from ditch, built up berm to assist water from flowing onto road, rebuilt rock armor in drainage.
This section does not have a culvert Berry intends to install trap and culvert in the spring of 2021.

Operator Comment: Sediment control measures (i.e. sediment traps, roadside ditches, check dams, berms) are in place and maintained throughout the interim roads and well pads to control potential sediment discharge associated with tracking from one dirt road onto another. These BMPs have been specifically engineered and certified by a professional engineer for these types of dirt roads.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Cleaned sediment from ditch, built up berm to assist water from flowing onto road, rebuilt rock armor in drainage. This section does not have a culvert Berry intends to install trap and culvert in the spring of 2021. Sediment control measures (i.e. sediment traps, roadside ditches, check dams, berms) are in place and maintained throughout the interim roads and well pads to control potential sediment discharge associated with tracking from one dirt road onto another. These BMPs have been specifically engineered and certified by a professional engineer for these types of dirt roads.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Don Wilbourn

Signed: _____

Title: Prod. Foreman

Date: 2/3/2021 12:42:15 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402590480	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files