

# TEP ROCKY MOUNTAIN LLC

## Chevron GM 442-20

### Location # 335402



Location shows signs of lack of stabilization BMP's in some areas (rutting is present).

**TEP ROCKY MOUNTAIN LLC  
Chevron GM 442-20  
Location # 335402**



**Location shows signs of lack of stabilization  
BMP's in some areas (rutting is present).**



**Location shows signs of lack of stabilization  
BMP's in some areas (rutting is present).**