

Issue Report

Trade Winds South 1-27, 061-06874



Report created on February 9, 2021

Captured: February 1, 2021



Type	Count
Erosion	4

No.	Summary	Type	Created	Status
4	South side of location with stressed vegetation with some wind erosion.	Erosion	Feb 9, 2021 at 3:33pm	Open
3	Minimal stressed vegetation with drifting dirt (Wind Erosion).	Erosion	Feb 9, 2021 at 3:30pm	Open
2	Minimal stressed vegetation with drifting dirt (Wind Erosion).	Erosion	Feb 9, 2021 at 3:29pm	Open
1	Minimal stressed vegetation with drifting dirt (Wind Erosion).	Erosion	Feb 9, 2021 at 3:28pm	Open

Erosion

No. 1 OPEN

Captured: Feb 1, 2021 at 10:34am

**Type**

Erosion

Lat/Long

38.46036, -102.67268

Summary

Minimal stressed vegetation with drifting dirt (Wind Erosion).

Created

Feb 9, 2021 at 3:28pm by Craig Quint

No. 2 OPEN*Captured: Feb 1, 2021 at 10:34am***Type**

Erosion

Lat/Long

38.46052, -102.67291

Summary

Minimal stressed vegetation with drifting dirt (Wind Erosion).

Created

Feb 9, 2021 at 3:29pm by Craig Quint

No. 3 OPEN

Captured: Feb 1, 2021 at 10:34am

**Type**

Erosion

Lat/Long

38.46012, -102.67286

Summary

Minimal stressed vegetation with drifting dirt (Wind Erosion).

Created

Feb 9, 2021 at 3:30pm by Craig Quint

No. 4 OPEN*Captured: Feb 1, 2021 at 10:34am***Type**

Erosion

Lat/Long

38.46012, -102.67241

Summary

South side of location with stressed vegetation with some wind erosion.

Created

Feb 9, 2021 at 3:33pm by Craig Quint

