


Issue Report



Knight #457362

Report created on February 19, 2021

Captured: February 17, 2021



Type	Count
Other	1

No.	Summary	Type	Created	Status
1	Open/Candlestick flare. Drilling corrective action: 903 b. (3) Combustors will be located a minimum of 100 feet from the nearest surface hole location and enclosed.	Other	Feb 19, 2021 at 2:25pm	Open

Other

No. 1 OPEN

Captured: Feb 17, 2021 at 12:21pm



Type

Other

Lat/Long

40.19786, -105.04206

Summary

Open/Candlestick flare. Drilling corrective action: 903 b. (3) Combustors will be located a minimum of 100 feet from the nearest surface hole location and enclosed.

Created

Feb 19, 2021 at 2:25pm by Adam Kraich

