

Document Number:
402605428

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 69175 Contact Name: Valerie Danson
 Name of Operator: PDC ENERGY INC Phone: (970) 506-9272
 Address: 1775 SHERMAN STREET - STE 3000 Fax: _____
 City: DENVER State: CO Zip: 80203 Email: valerie.danson@pdce.com

For "Intent" 24 hour notice required, Name: _____ Tel: _____
 Email: _____

COGCC contact: _____

Type of Well Abandonment Report: Notice of Intent to Abandon Subsequent Report of Abandonment

API Number 05-123-23589-00
 Well Name: PHINNEY Well Number: 34-10
 Location: QtrQtr: SWSE Section: 10 Township: 6N Range: 64W Meridian: 6
 County: WELD Federal, Indian or State Lease Number: _____
 Field Name: WATTENBERG Field Number: 90750

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.494810 Longitude: -104.534500
 GPS Data: GPS Quality Value: 1.7 Type of GPS Quality Value: _____ Date of Measurement: 12/14/2006

Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other _____

Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	6950	6960	01/18/2021	B PLUG CEMENT TOP	6900

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J55	24	0	578	410	578	0	VISU
1ST	7+7/8	4+1/2	J55	10.5	0	7103	175	7103	6318	CBL
S.C. 1.1						6318	270	6318	2730	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 6900 with 2 sacks cmt on top. CIBP #2: Depth 6584 with 2 sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 100 sks cmt from 2550 ft. to 2300 ft. Plug Type: STUB PLUG Plug Tagged:
 Set 100 sks cmt from 1680 ft. to 1480 ft. Plug Type: OPEN HOLE Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set 375 sacks half in. half out surface casing from 778 ft. to 0 ft. Plug Tagged:
 Set _____ sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: 2500 ft. of 4+1/2 inch casing Number of Days from Setting Surface Plug to Capping or Sealing the Well: 9
 Surface Plug Setting Date: 01/19/2021 Cut and Cap Date: 01/28/2021
 *Wireline Contractor: Rocky Mtn Wireline Services *Cementing Contractor: DUCO Inc. Cementing Services
 Type of Cement and Additives Used: Class G 15.8 PPG Cement
 Flowline/Pipeline has been abandoned per Rule 1105 Yes No

Technical Detail/Comments:

Phinney 34-10 (05-123-23589)/Plugging Procedure
 Producing Formation: Codell: 6950'-6960'
 Upper Pierre Aquifer: 550'-1580'
 TD: 7136' PBTD: 7088' (2/1/2018)
 Surface Casing: 8 5/8" 24# @ 578' w/ 410 sxs cmt
 Production Casing: 4 1/2" 10.5# @ 7103' w/ 445 sxs cmt (TOC @ 2730' - CBL)

Procedure:
 1. MIRU pulling unit. Pull 2 3/8" tubing.
 2. RU wireline company.
 3. TIH with CIBP. Set BP at 6900'. Top with 2 sxs 15.8#/gal CI G cement. (Top of Codell perms @ 6950')
 4. TIH with CIBP. Set BP at 6584'. Top with 2 sxs 15.8#/gal CI G cement. (Top of Niobrara @ 6634')
 5. Ran a Strip Log from 2500' to Surface (for casing cut verification, log not kept).
 6. TIH with casing cutter. Cut 4.5" casing at 2500'. Pull cut casing.
 7. TIH with tubing to 2550'. RU cementing company. Mix and pump 100 sxs 15.8#/gal CI G cement down tubing. (Stub plug from 2550'-2300') TOC at 2300'.
 8. Wait a sufficient time to confirm static conditions. If at any time after placing this plug there is evidence of pressure or fluid migration, contact engineering before continuing operations
 9. TIH with tubing to 1680'. Mix and pump 100 sxs 15.8#/gal CI G cement down tubing. (Pierre coverage from 1680'-1480'). TOC at 1480'.
 10. Pick up tubing to 778'. Mix and pump 375 sxs 15.8#/gal CI G cement down tubing. Cement circulate to surface.
 11. Cut surface casing 6' below ground level and weld on cap.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Valerie Danson

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____

COA Type	Description

Attachment List

Att Doc Num	Name
402605431	CEMENT JOB SUMMARY
402605432	OTHER
402605433	OPERATIONS SUMMARY
402605434	WELLBORE DIAGRAM

Total Attach: 4 Files

General Comments

User Group	Comment	Comment Date
		Stamp Upon Approval

Total: 0 comment(s)