

The corrective action for the erosion noted is March 11, 2021. The area is very muddy, 5 rock socks were placed in the wash out and completed a rock armoring of the entire length of the errored area.

