

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402566662

Date Received:

01/05/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

.Grizzly

sghan@grizzlyenergyllc.com

.Grizzly

aaxelson@grizzlyenergyllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700702030

Inspection Date: 12/15/2020

FIR Submit Date: 12/15/2020

FIR Status: _____

Inspected Operator Information:

Company Name: GRIZZLY OPERATING LLC

Company Number: 10531

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 335173

Location Name: JOLLEY-66S91W Number: 20NWNE County: _____

Qtrqtr: NWNE Sec: 20 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.518390 Longitude: -107.576140

FACILITY - API Number: 05-045-00 Facility ID: 335173

Facility Name: JOLLEY-66S91W Number: 20NWNE

Qtrqtr: NWNE Sec: 20 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.518390 Longitude: -107.576140

CORRECTIVE ACTIONS:

1 ☒ CA# 145153

Corrective Action: remove debris

Date: 01/15/2021

Response: CA COMPLETED

Date of Completion: 12/17/2020

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 145154

Corrective Action: Maintain ALL BMP's
Provide proof of tracking control BMP's

Date: 01/15/2021

Response: CA COMPLETED

Date of Completion: 01/05/2021

Operator Comment: This comment is specific to the CA associated with the cut slope near the separators and referenced in the Field Inspection Report. This CA is not complete and cannot be completed by the assigned CA deadline due to seasonal weather conditions. The alleged slope stabilization issue near the separators will be addressed when onsite and winter weather conditions allow.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Scott Ghan

Signed:

Title: Senior EHS Specialist

Date: 1/5/2021 2:33:15 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402566662	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files