

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17SENE
Location # 324184**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17SENE
Location # 324184**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17SENE
Location # 324184**



**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17SENE
Location # 324184**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17SENE
Location # 324184**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**