

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402602225

Date Received:

02/17/2021

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed

1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 51130

Name of Operator: LOCIN OIL CORPORATION

Address: 2445 TECHNOLOGY FOREST BD #710

City: THE WOODLANDS State: TX Zip: 77381

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Nicol, Michael

281-362-8600x116

mnicol@locinoil.com

Thompson, Bud

BLThomps@BLM.gov

COGCC INSPECTION SUMMARY:

FIR Document Number: 700405377

Inspection Date: 02/08/2021

FIR Submit Date: 02/16/2021

FIR Status: _____

Inspected Operator Information:

Company Name: LOCIN OIL CORPORATION

Company Number: 51130

Address: 2445 TECHNOLOGY FOREST BD #710

City: THE WOODLANDS State: TX Zip: 77381

LOCATION - Location ID: 315397

Location Name: FORK UNIT FEDERAL-61S101W Number: 19SENW County: RIO BLANCO

Qtrqr: SENW Sec: 19 Twp: 1S Range: 101W Meridian: 6

Latitude: 39.949867 Longitude: -108.777717

FACILITY - API Number: 05-103-00 Facility ID: 230771

Facility Name: FORK UNIT FEDERAL Number: 6-19-1-1W

Qtrqr: SENW Sec: 19 Twp: 1S Range: 101W Meridian: 6

Latitude: 39.949867 Longitude: -108.777717

CORRECTIVE ACTIONS:

1 ☒ CA# 146595

Corrective Action: Provide bradenhead access with appropriate fittings to allow determination of pressure and fluid flow.

Date: 02/08/2021

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

For the safety of the field personnel the well was constructed with the bradenhead access buried and currently below ground level. This method of well construction allowed the field personnel to access the well head without

Operator Comment: the use of stairs and platform, thereby minimizing the risk of falls and injuries and eliminating cellars that could result in injury to people and wildlife.

Locin wishes to comply with the revised Rules and Regulations quickly in a safe environment. Currently, due to the winter season, the ground around the wellheads and bradenhead access is covered with frozen soil. Any attempt to dig out the soil at this time will require additional effort other than an easy shovel or backhoe. We will need to use a chisel and be aggressive with the back hoe. This additional force necessary to dig out the bradenhead access will create an unsafe situation for the field personnel, contractors and the individual wells.

Therefore, we respectfully request time until May 31, 2021 to repair/revise the access to the bradenhead while insuring we protect the health and safety of the public and wildlife (near and long term).

COGCC Decision: **Not Approved**

COGCC Representative:

COGCC Supervisor:

Operator has not made the corrective actions, as required.

OPERATOR COMMENT AND SUBMITTAL

Comment: For the safety of the field personnel the well was constructed with the bradenhead access buried and currently below ground level. This method of well construction allowed the field personnel to access the well head without the use of stairs and platform, thereby minimizing the risk of falls and injuries and eliminating cellars that could result in injury to people and wildlife.

Locin wishes to comply with the revised Rules and Regulations quickly in a safe environment. Currently, due to the winter season, the ground around the wellheads and bradenhead access is covered with frozen soil. Any attempt to dig out the soil at this time will require additional effort other than an easy shovel or backhoe. We will need to use a chisel and be aggressive with the back hoe. This additional force necessary to dig out the bradenhead access will create an unsafe situation for the field personnel, contractors and the individual wells.

Therefore, we respectfully request time until May 31, 2021 to repair/revise the access to the bradenhead while insuring we protect the health and safety of the public and wildlife (near and long term).

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Nicol

Signed:

Title: Manager

Date: 2/17/2021 6:09:05 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402602225	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files