

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/08/2021

Submitted Date:

03/12/2021

Document Number:

690201261

FIELD INSPECTION FORMLoc ID 308043 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD State: CO Zip: 8111-

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		efitzgerald@ogrisop.com	
		timothy.thomsen@state.co.us	
		rmack@ogrisop.com	
ATWATER BONNIE		batwater@ogrisop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260445	WELL	PR	08/15/2011	GW	071-07437	APACHE CANYON 11-12V	RI

General Comment:

This is a stormwater management inspection.
See attached photos and additional details within this report.

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is vehicle rutting along the main road. There are areas of the road that are not stabilized and stormwater is not properly diverted. Repairing the road only by grading is not sufficient. Areas of rutting need to be stabilized with gravel and compaction. This issue has been previously observed and needs to be prevented. BMP's must be implemented in accordance with good engineering practice and must be maintained.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 04/30/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
An extended CA date is provided due to weather conditions.	CostaR	03/12/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690201262	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5374842