

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402593688

Date Received:
02/08/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Patterson, Chris</u>		<u>spwu@chevron.com</u>
<u>Olson, Andrew</u>		<u>andrewolson@chevron.com</u>
<u>Sandford, Anita</u>		<u>ATLX@chevron.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202230

Inspection Date: 01/19/2021

FIR Submit Date: 01/22/2021

FIR Status: _____

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

LOCATION - Location ID: 397191

Location Name: UNION PACIFIC-62N102W Number: 29SENW County: _____

Qtrqtr: SENW Sec: 29 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.115865 Longitude: -108.869776

FACILITY - API Number: 05-103-00 Facility ID: 397191

Facility Name: UNION PACIFIC-62N102W Number: 29SENW

Qtrqtr: SENW Sec: 29 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.115865 Longitude: -108.869776

CORRECTIVE ACTIONS:

1 CA# 146051

Corrective Action: CA from Inspection #692401238: Remove debris & remnants of concrete Pad from Location; reclaiming/re-seeding disturbed areas as necessary.

Date: 11/01/2019

Response: CA COMPLETED

Date of Completion: 02/04/2021

Operator Comment: UP 52-29 concrete removed and site reclaimed will need reseeded this summer. Please see attached photo.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: UP 52-29 concrete removed and site reclaimed will need reseeded this summer. Please see attached photo.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris patterson

Signed: _____

Title: Lead HSE Specialist

Date: 2/8/2021 9:56:23 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402593688	FIR RESOLUTION SUBMITTED
402593702	Photo

Total Attach: 2 Files