

Document Number:
 402599750
 Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 72400 Contact Name: Jeff Schneider
 Name of Operator: PUBLIC SERVICE COMPANY OF COLORADO Phone: (970) 867-9437
 Address: 1123 W 3RD AVE Fax: (970) 867-9137
 City: DENVER State: CO Zip: 80223 Email: jeff@schneiderenergy.com

For "Intent" 24 hour notice required, Name: Schure, Kym Tel: (970) 520-3832
COGCC contact: Email: kym.schure@state.co.us

Type of Well Abandonment Report: Notice of Intent to Abandon Subsequent Report of Abandonment

API Number 05-087-07091-00
 Well Name: STORAGE UNIT Well Number: 23
 Location: QtrQtr: SWNE Section: 28 Township: 2N Range: 60W Meridian: 6
 County: MORGAN Federal, Indian or State Lease Number: _____
 Field Name: ROUNDUP Field Number: 74950

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.111560 Longitude: -104.101030
 GPS Data: GPS Quality Value: 1.7 Type of GPS Quality Value: _____ Date of Measurement: 06/30/2010
 Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other This is a observation well for gas storage field that is no longer
 Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
J-3 SAND	6514	6524			
Total: 1 zone(s)					

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	K-55	24	0	233	190	190	0	VISU
1ST	7+7/7	4+1/2	K-55	10.5	0	6595	1530	6595	0	VISU

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 6464 with 2 sacks cmt on top. CIBP #2: Depth 5500 with 2 sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 10 sks cmt from 2500 ft. to 2400 ft. Plug Type: CASING Plug Tagged:
 Set 15 sks cmt from 283 ft. to 50 ft. Plug Type: CASING Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Perforate and squeeze at 283 ft. with 0 sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)
 Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:
 Set 15 sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Number of Days from Setting Surface Plug to Capping or Sealing the Well: _____
 Surface Plug Setting Date: _____ Cut and Cap Date: _____
 *Wireline Contractor: _____ *Cementing Contractor: _____
 Type of Cement and Additives Used: _____
 Flowline/Pipeline has been abandoned per Rule 1105 Yes No

Technical Detail/Comments:

The production casing on this well was cemented with 1280 sacks of Halco Lite and 250 sacks of 50/50 Poz Mix cement on 9/19/1980. Good returns were seen at surface during the original cement job. There is no CBL in the well files. We plan on running a CBL after running the CIBP @ 6464' and running the CBL to top of the cement or surface. The log will be emailed to the COGCC Engineer and we will not proceed with the plugging operations until given approval by the COGCC Engineer.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Jeff Schneider
 Title: Consultant Date: _____ Email: jeff@schneiderenergy.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: _____

COA Type	Description

Attachment List

Att Doc Num

Name

402636594

WELLBORE DIAGRAM

402637035

WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

User Group

Comment

Comment Date

Stamp Upon
Approval

Total: 0 comment(s)