

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/24/2021

Submitted Date:

03/24/2021

Document Number:

693504887

FIELD INSPECTION FORM

Loc ID 330987 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
	303-825-4822	cogcc@kpk.com	All inspections
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257529	WELL	PR	10/23/2000	OW	123-19990	ROCKY MOUNTAIN FUEL CO 15-9	PR

General Comment:

Inspected Facilities

Facility ID: 257529 Type: WELL API Number: 123-19990 Status: PR Insp. Status: PR

Complaint

Comment: Inspection in response to complaint.
 Field Inspector Assigned: Randy Silver
 Complaint Received
 Date: 3-23-2021
 Complaint Contacted: yes via phone
 Date: 3-23-2021 Time: 10:00AM
 Location ID # 330987
 Location name: Rocky Mountain Fuel CO 15-9
 Inspection Document # 693504881
 Complaint Document #200449476
 Nature of Complaint: noise
 Field Inspector Actions:
 On 3-23-2021, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to Noise. The complainant Lynn Johns 8690 County Road 10 stated the issues were occurring outside of complainants home.
 On 3-23-2021, I attempted to make contact with the complainant who indicated that on 3-18-2021 experiencing a squealing sound from the pump unit to the north of complainants home. Noise usually occurs during nighttime hours.
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, Pumping Unit was not running so I could not hear any noise. I spoke with KPK supervisor he stated he would look at timer and see if he can run it during day light hours and find source of noise. I time of inspection road was not assessable due to weather condition and no gravel on road. Inspector will be going out periodically to location to try to find source of noise.
 No violation of COGCC rules were observed at the time of the inspection.
 All information reviewed and site inspection information has been submitted to the COGCC for further review.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
No violation of COGCC rules were observed at the time of the inspection. Inspector will be going to location periodically to try to find the source of noise.	silverr	03/24/2021