

Inspection Photos

3/25/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335145

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335145



Photo 1: Photo taken from the south end of the Location, facing north. Photo shows that control measures to stabilize/protect unpaved areas of the Location are missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335145



Photo 2: Photo taken from the north end of the Location, facing southeast. Photo shows that control measures to stabilize/protect unpaved areas of the Location are missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335145



Photo 3: Photo taken from the north end of the Location, facing southeast. Photo shows that control measures to stabilize/protect unpaved areas of the Location are missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335145



Photo 4: Photo taken from the slopes on the west end of the Location. Photo shows that control measures to stabilize/protect the cut/fill slopes of the Location are missing or insufficient; Gully erosion evident; crack forming within slope. 6 foot measuring stick used for reference.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335145



Photo 5: Photo taken from the slopes on the west end of the Location. Photo shows that control measures to stabilize/protect the cut/fill slopes of the Location are missing or insufficient; Gully erosion evident; crack forming within slope. 6 foot measuring stick used for reference.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335145



Photo 6: Photo taken from the slopes on the west end of the Location. Photo shows that control measures to stabilize/protect the cut/fill slopes of the Location are missing or insufficient; Gully erosion evident; crack forming within slope.