

TEP
RMV 14-29
Location # 323922

Mar 31, 2021 at 10:40:09 AM
39.500725,-107.903593 ±4.79m
COGCC



location

Mar 31, 2021 at 10:40:50 AM
39.500777,-107.903319 ±4.75m
COGCC



location

TEP
RMV 14-29
Location # 323922



Lack of stabilization/compaction

TEP
RMV 14-29
Location # 323922



Lack of stabilization/compaction



Erosion over culvert at entrance

TEP
RMV 14-29
Location # 323922



Erosion over culvert at entrance



Entrance to location over culvert arrow is location of erosion

