

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/01/2021

Submitted Date:

04/01/2021

Document Number:

699502492

**FIELD INSPECTION FORM**Loc ID 320225 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 31257

Name of Operator: FRITZLER RESOURCES INC

Address: P O BOX 114

City: FORT MORGAN State: CO Zip: 80701

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccenforcement@state.co.us	
Fritzler, Gene	970-768-0845	gfritzler@bresnan.net	left msg 9/21

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203117	WELL	SI	02/01/2016	GW	001-08525	LINNEBUR 24-1	SI

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	road is not maintained very well		
Corrective Action	L	Date:	

Overall Good: ☐

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	No bird protector on separator		
Corrective Action:	Install or repair wildlife protection equipment Comply with rule 324 A.a	Date:	05/20/2019
Type	OTHER		
Comment:	No sign at wellhead		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/06/2017
Type	OTHER		
Comment:	No placards on tank/volume/sign		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/06/2017
Type	OTHER		
Comment:	Berms need to be repaired around tank		
Corrective Action:	Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.	Date:	10/06/2017

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
	1		STEEL AST		,
Comment: <input type="text"/>					

Corrective Action:				Date:	
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**

Facility ID: 203117 Type: WELL API Number: 001-08525 Status: SI Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: no bradenhead test data on COGCC database. Contact COGCC engineering.

04/09/2021

Corrective Action: Comply with annual bradenhead testing rules.

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 3/31/21 at approximately 1300 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Linnebur 24-1</p> <p>Company Name- Fritzler Resources</p> <p>API- 05-001-08525</p> <p>In Adams County Colorado.</p> <p>While there, I observed SI well.</p> <p>This is a follow up inspection for Document # 685503722 &amp; 88400352 &amp; 685100935 &amp; 685101426 corrective actions from these inspections are delinquent.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Berms need to be repaired around tank</p> <p>Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B. 10/6/17</p> <p>No placards on tank/volume/sign</p> <p>Install sign to comply with Rule 210.d. 10/6/17</p> <p>No sign at wellhead</p> <p>Install sign to comply with Rule 210.d. 10/6/17</p> <p>No bird protector on separator</p> <p>Install or repair wildlife protection equipment Comply with rule 324 A.a 5/20/19</p> <p>no bradenhead test data on COGCC database. Contact COGCC engineering.</p> <p>Comply with annual bradenhead testing rules. 4/9/21</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	04/01/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699502493	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391925">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391925</a>