

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402646185

Date Received:
04/01/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10550
Name of Operator: MUSTANG RESOURCES LLC
Address: 1660 LINCOLN STREET SUITE 1450
City: DENVER State: CO Zip: 80264

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Deb Lemon</u>	<u>3038075112</u>	<u>dlemon@mustangresourcesllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 692403023
Inspection Date: 02/10/2021 FIR Submit Date: 02/15/2021 FIR Status: _____

Inspected Operator Information:

Company Name: MUSTANG RESOURCES LLC Company Number: 10550
Address: 1660 LINCOLN STREET SUITE 1450
City: DENVER State: CO Zip: 80264

LOCATION - Location ID: 323788

Location Name: MOORE-66S94W Number: 27SENE County: GARFIELD
Qtrqr: SENE Sec: 27 Twp: 6S Range: 94W Meridian: 6
Latitude: 39.499199 Longitude: -107.867203

FACILITY - API Number: 05-045-00 Facility ID: 210809

Facility Name: MOORE Number: 27-42-6S-94W
Qtrqr: SENE Sec: 27 Twp: 6S Range: 94W Meridian: 6
Latitude: 39.499199 Longitude: -107.867203

CORRECTIVE ACTIONS:

1 CA# 146648

Corrective Action: Remove Debris from Location. Date: 03/16/2021

Response: CA COMPLETED Date of Completion: 03/30/2021

Operator Comment: Delay in work due to weather.

COGCC Decision: _____

COGCC
Representative:

2 CA# 146649

Corrective Action: Assess location vegetation once Debris weeds are removed. Conduct any activities necessary as indicated by assessment, (ie: de-compacting, amending, re-seeding/inter-seeding or other) to insure establishment of desirable Vegetation in Interim areas of site. Reclamation activities to be complete by 5/1/21. Adaptive Weed control program for site needs to be developed.

Date: 05/01/2021

Response: CA COMPLETED

Date of Completion: 03/30/2021

Operator Comment: Delay in work due to weather. Mustang continues to work with the surface owner and complete work suitable to the owner. The owner is planting his own seed and does not want Mustang to interfere. On 3/30, Mustang removed weeds and trimmed what the owner would like left in place.

COGCC Decision: _____

COGCC
Representative:

3 CA# 146650

Corrective Action: Install/repair/maintain required BMPs per Rule 1002.f., stabilizing pad.

Date: 03/16/2021

Response: CA COMPLETED

Date of Completion: 03/30/2021

Operator Comment: See #2.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Mustang continues to work within surface owner constraints.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Deb Lemon

Signed: _____

Title: Regulatory Manager

Date: 4/1/2021 11:49:21 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402646201	Photo #1 Brian Speary well pad - Moore
-----------	--

Total Attach: 1 Files