

TEP
RMV 96-28
Location # 335122



location



location

TEP
RMV 96-28
Location # 335122



location



Lack of stabilization on cut slope



TEP
RMV 96-28
Location # 335122



Lack of stabilization on cut slope



TEP
RMV 96-28
Location # 335122



Lack of stabilization on cut slope



TEP
RMV 96-28
Location # 335122



Lack of stabilization on cut slope