

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402644760

Date Received:
03/31/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: THREE ALLEN CENTER, 333 CLAY ST SUITE 3900

City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693902883

Inspection Date: 02/22/2021

FIR Submit Date: 02/23/2021

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: THREE ALLEN CENTER, 333 CLAY ST SUITE 3900

City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 326611

Location Name: MILLER FEDERAL GAS UNIT-N35N7W Number: 33NWNE County: LA PLATA

Qtrqr: NWNE Sec: 33 Twp: 35N Range: 7W Meridian: N

Latitude: 37.262074 Longitude: -107.638970

FACILITY - API Number: 05-067-00 Facility ID: 258939

Facility Name: MILLER FEDERAL Number: 2

Qtrqr: NWNE Sec: 33 Twp: 35N Range: 7W Meridian: N

Latitude: 37.262074 Longitude: -107.638970

CORRECTIVE ACTIONS:

1 CA# 146803

Corrective Action:

Date: 10/09/2015

Weeds need to be controlled. Areas with weed infestation and the majority of the reclamation area needs revegetation. Livestock exclusion may be needed for successful vegetation establishment. Followup vegetation and weed monitoring as well as subsequent treatment are required. Monitoring data may be requested. Corrective action is back-dated to document duration of non-compliance (10/9/2015).

New corrective action (in addition to action above): Submit a weed control and revegetation plan by 3/31/2021 with a detailed and site specific schedule for treatments, weed control and revegetation methods, seed mix, mulching, monitoring to control infestation and stabilize location.

Response: CA COMPLETED

Date of Completion: 03/31/2021

Operator Comment: See Attached Weed Management Plan of site.

COGCC Decision: Approved pending re-inspection

COGCC Representative: -herbicide treatment in the spring after seeding will likely result in desirable seedling mortality. Mechanical or manual methods of treating weeds right after seeding may better prevent seedling mortality.
-Plan indicates that hydromulch "is recommended". Inspector recommends mulching such as a high quality hydromulch or crimped long stem hay at any time seeding is conducted. Soil protection is required on bare soils.
-This plan satisfies the corrective action to submit a weed control plan. Operator needs to control infestation in a timely manner in order to bring location into compliance for weeds.

OPERATOR COMMENT AND SUBMITTAL

Comment: see attached plan

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Karin Rhodes

Signed: _____

Title: admin asst

Date: 3/31/2021 12:29:55 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402644760	FIR RESOLUTION SUBMITTED
402644764	weed mgmt plan for Miller Fed 2

Total Attach: 2 Files