

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/01/2021

Submitted Date:

04/01/2021

Document Number:

699502496

**FIELD INSPECTION FORM**Loc ID 319737 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 31257

Name of Operator: FRITZLER RESOURCES INC

Address: P O BOX 114

City: FORT MORGAN State: CO Zip: 80701

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fritzler, Gene	970-768-0845	gfritzler@bresnan.net	left msg 9/21
Leonard, Mike		mike.leonard@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201199	WELL	PR	09/01/2020	OW	001-06602	LINNEBUR 1	PR

**General Comment:**

**Location****Lease Road:**

Type	Access		
comment:	Unable to access well inside of elk farm.		
Corrective Action:	Provide key, combination, or alternate method of access to comply with rule 204	Date:	04/01/2021

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 201199 Type: WELL API Number: 001-06602 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: Fluid Type:

End Surf Csg Pressure:

Comment: No bradenhead test on fiel. Contact COGCC engineering

Corrective Action: Comply with COGCC annual bradenhead testing rules 4/9/21

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 3/31/21 at approximately 1300 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Linnebur 1</p> <p>Company Name- Fritzler Resources</p> <p>API- 05-001-06602</p> <p>In Adams County Colorado.</p> <p>While there, I observed unaccusable well</p> <p>No bradenhead test on file. Contact COGCC engineering.</p> <p>Comply with COGCC annual bradenhead testing rules.4/9/21</p> <p>Unable to access well inside of elk farm.</p> <p>Provide key, combinations, or alternate method of access to comply with rule 204.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	04/01/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402645823	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391931">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391931</a>
699502497	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391927">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391927</a>