

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402652167

Date Received:

04/07/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

batwater@ogrisop.com

rmack@ogrisop.com

efitzgerald@ogrisop.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690201284

Inspection Date: 03/11/2021

FIR Submit Date: 03/18/2021

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 308455

Location Name: HILL RANCH-635S67W Number: 7NESE County: LAS ANIMAS

Qtrqtr: NESE Sec: 7 Twp: 35S Range: 67W Meridian: 6

Latitude: 37.010850 Longitude: -104.923370

FACILITY - API Number: 05-071- -00 Facility ID: 272337

Facility Name: HILL RANCH Number: 7-9

Qtrqtr: NESE Sec: 7 Twp: 35S Range: 67W Meridian: 6

Latitude: 37.010850 Longitude: -104.923370

CORRECTIVE ACTIONS:

1 ☒ CA# 147480

Corrective Action: Comply with Rule 606

Date: 04/20/2021

Response: CA COMPLETED

Date of Completion: 03/31/2021

THE BROKEN DOOR AND DOOR PARTS WERE REMOVED FROM THE LOCATION. SEE ATTACHED PHOTO LOG FOR DETAILS.

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 147481

Corrective Action: Implement or modify BMPs for improved material handling and spill prevention.
Immediately clean up area.

Date: 04/20/2021

Response: CA COMPLETED

Date of Completion: 03/31/2021

Operator
Comment:

THE HYDRAULIC STAIN NEAR THE ENGINE SKID WAS REMOVED FROM LOCATION. SEE ATTACHED
PHOTO LOG FOR DETAILS.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 147482

Corrective Action: Maintain the fence.

Date: 04/20/2021

Response: CA COMPLETED

Date of Completion: 03/31/2021

Operator
Comment:

THE ELECTRIC FENCE WAS REPAIRED. SEE ATTACHED PHOTO LOG FOR DETAILS.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CORRECTIVE ACTIONS HAVE BEEN ADDRESSED.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: Sr. Environmental Tech.

Date: 4/7/2021 5:18:54 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402652167	FIR RESOLUTION SUBMITTED
402652172	PHOTO LOG

Total Attach: 2 Files