

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/01/2021

Submitted Date:

04/02/2021

Document Number:

689501173

**FIELD INSPECTION FORM**
 Loc ID 333225 Inspector Name: Brown, Kari On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>
MacLaren, Joe		joe.maclaren@state.co.us	
,		mknop@kpk.com	
Canfield, Chris		chris.canfield@state.co.us	

**General Comment:**

This is an environmental inspection in response to Initial Form 19 Doc#402644033 submitted 3/30/2021 when surface soil staining was observed in the vicinity of a buried flowline. There were no operator or contract environmental personnel on location at the time of this field inspection

Inspection of spill area only, not of nearby facilities. Any corrective actions from previous inspections that have not been addressed are still applicable.

Photo attached to document site conditions.

**Environmental****Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: \_\_\_\_\_

Comment: Initial Form 19 Doc#402644033 documents a spill discovery date of 3/29/2021. Hydrocarbon fluids remain on the surface, no work has been initiated for spill investigation or remediation.

Corrective Action: In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered. In accordance with Rule 912.b.(4), the Operator shall make a supplemental report on Form 19 not more than 10 calendar days after the spill/release is discovered that includes: A topographic map showing the governmental section and location of the spill or an aerial photograph showing the location of the spill; All pertinent information about the spill/release known to the Operator that has not been reported previously including photo documentation showing the source of the Spill or Release, the impacted area, and initial cleanup activity; Information relating to the initial mitigation, site investigation, and remediation measures conducted by the Operator (4/8/2021). In accordance with Rule 912.a.(6) No later than 90 days after a Spill or Release is discovered Operator will submit a Form 19 – Supplemental requesting closure pursuant to Rule 913.h and supported by adequate documentation to demonstrate closure or a Form 27 Workplan with a timeline for investigation and closure of this release. If Remediation will continue under an approved Form 27, also submit a Form 19 – Supplemental requesting closure of this spill referencing the approved Remediation workplan (6/27/2021).

Date: 03/29/2021

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402647235	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5393233">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5393233</a>
689501174	Field Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5393193">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5393193</a>