

**Inspection Photos**  
**Location Name: Bighole-Fed Land Bank 13-1**  
**Location ID: 312931**



**Photo 1. Fluid removed. Stained soil remains.  
Unconsolidated material used in attempted berm repair.**



**Photo 2. Unconsolidated material used in attempted berm repair. Stained soil.**



**Inspection Photos**  
**Location Name: Bighole-Fed Land Bank 13-1**  
**Location ID: 312931**



**Photo 3. Leak stopped. Fluid removed. Stained soil remains.**



**Photo 4. Fresh weld in apparent “repair” of flowline where leak was occurring.**

**Inspection Photos**  
**Location Name: Bighole-Fed Land Bank 13-1**  
**Location ID: 312931**



**Photo 5. Fluid and stained soil in north side of berm.**



**Photo 6. Stained soil in berm.**



**Inspection Photos**  
**Location Name: Bighole-Fed Land Bank 13-1**  
**Location ID: 312931**



**Photo 7. Stained soil in berm.**



**Photo 8. Stained soil in berm.**

**Inspection Photos**  
**Location Name: Bighole-Fed Land Bank 13-1**  
**Location ID: 312931**



**Photo 9. Spill path clean-up. Some areas appear to have fresh soil placed over stained soil.**



**Photo 10. Spill path clean-up.**

**Inspection Photos**  
**Location Name: Bighole-Fed Land Bank 13-1**  
**Location ID: 312931**



**Photo 11. Stained soil remains in spill path.**



**Photo 12. Stained soil remains in spill pathway. It does not appear that clean-up addressed full extent of release.**

