


TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W 25SWW Location # 335097



Deadman markers are knocked over.

**TEP ROCKY MOUNTAIN LLC
FEDERAL-66S96W 25SWSW
Location # 335097**



Deadman markers are knocked over.

**TEP ROCKY MOUNTAIN LLC
FEDERAL-66S96W 25SWSW
Location # 335097**



Perimeter ditch needs cleaned out.

**TEP ROCKY MOUNTAIN LLC
FEDERAL-66S96W 25SWSW
Location # 335097**



Ditches between location and battery need maintained.

**TEP ROCKY MOUNTAIN LLC
FEDERAL-66S96W 25SWSW
Location # 335097**



Battery sign is not at tank battery.

**TEP ROCKY MOUNTAIN LLC
FEDERAL-66S96W 25SW SW
Location # 335097**



Inlet basin of culvert needs maintained.

**TEP ROCKY MOUNTAIN LLC
FEDERAL-66S96W 25SW SW
Location # 335097**



**Culvert needs maintained/repaired.
39.48725 108.06422**



Culverts are not jointed together.

**TEP ROCKY MOUNTAIN LLC
FEDERAL-66S96W 25SW SW
Location # 335097**



**Culverts are not jointed together. Unstable ground around culvert.
39.48725 108.06422**