

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	fabricated angle iron		
Corrective Action:		Date:	
Type	OTHER		
Comment:	ncillary equipment has fabricated round stock and steel pipe		
Corrective Action:		Date:	

Equipment:

Type	Quantity	Comment	Corrective Action	Date	corrective date
Prime Mover	# 1	electric motor			
Pump Jack	# 1				
Ancillary equipment	# 1	Electric panel, meter box and transformers			
Bradenhead	# 1	appears to be plumbed to surface			

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 240594 Type: WELL API Number: 123-08382 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: 05/28/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 4-15-2021 at approximately 1020hrs , I, conducted an inspection of KPK well Paul Heinze #1 API # 05-123-08382 in Weld County Colorado. The purpose of this inspection was to confirm compliance with the COGCC Director's order under rule 901.a. of the Rules and Regulations of the Colorado Oil and Gas Conservation Commission, 2 CCR 404-1 ("Rule" or "Rules"). As part of this order the operator KPK (Operator No. 46290) was ordered to immediately suspend all production operations at these assigned location. I inspected this location and confirmed operations appeared to be suspended as equipment on site does appear to be shut off and valves appear to be closed. See attached photos in attachments of this inspection. On 4-14-2021 the operator KPK notified COGCC staff Jeremy Ferrin through email that all 87 locations listed in the order had suspended all production operations at these locations. All corrective action from previous and further inspection must be completed to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	04/15/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699303707	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5404887