

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402654582

Date Received:

04/11/2021

Spill report taken by:

NEIDEL, KRIS

Spill/Release Point ID:

440659

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: CHEVRON USA INC	Operator No: 16700	Phone Numbers Phone: (970) 675-3814 Mobile: (307) 871-5363 Email: spwu@chevron.com
Address: 100 CHEVRON ROAD		
City: RANGELY	State: CO Zip: 81648	
Contact Person: Chris Patterson		

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400758214

Initial Report Date: 12/23/2014 Date of Discovery: 12/20/2014 Spill Type: Recent Spill

Spill/Release Point Location:

QTRQTR SESE SEC 17 TWP 2N RNG 102W MERIDIAN 6

Latitude: 40.137600 Longitude: -108.860000

Municipality (if within municipal boundaries): County: RIO BLANCO

Reference Location:

Facility Type: ☐ Facility/Location ID No ☒ Well API No. (Only if the reference facility is well) 05-103-06122
Spill/Release Point Name: ☐ No Existing Facility or Location ID No.

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes
Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): >=5 and <100

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify:

Land Use:

Current Land Use: NON-CROP LAND Other(Specify):

Weather Condition: 30 degree

Surface Owner: OTHER (SPECIFY) Other(Specify): Atlas Resource Partners, L.P.

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

Saturday (12-20-2014) at approximately 5:30 PM a leak occurred on a 3" injection line due to internal corrosion on a cement line pipe at UP 55-17 (40.1376, -108.86009). Approximately 19 BBLs of produced water was released. Vacuum truck recovered an estimated 15 BBLs. The lateral valve was shut in immediately upon detection. Vacuum truck recovered an estimated 15 BBLs. The affected area will be water washed and soil samples will be taken.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
12/20/2014	COGCC	Kris Neidel	970-871-1963	Emailed
12/20/2014	CDPHE	Hotline	877-518-5608	LVM
12/20/2014	Rio Blanco County	Mark Sprague	970-878-9584	Emailed
12/20/2014	Chevron Land Rep	Shalyce Holmes	432-687-7348	Emailed

Was there a Grade 1 Gas Leak? Yes ☐ No ☐

If YES, enter the Document Number of the Grade 1 Gas Leak Report Form 44: _____

Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? Yes ☐ No ☐

If YES, enter the Document Number of the Initial Accident Report, Form 22: _____

Was there damage during excavation? Yes ☐ No ☐

If YES, was CO 811 notified prior to excavation? Yes ☐ No ☐

CORRECTIVE ACTIONS

#1 Supplemental Report Date: 04/11/2021

Root Cause of Spill/Release Corrosion

Other (specify) _____

Type of Equipment at Point of Spill/Release: Process Piping

If "Other" selected above, specify or describe here:

Describe Incident & Root Cause (include specific equipment and point of failure)

Saturday (12-20-2014) at approximately 5:30 PM a leak occurred on a 3" injection line due to internal corrosion on a cement line pipe at UP 55-17 (40.1376, -108.86009). Approximately 19 BBLs of produced water was released. Vacuum truck recovered an estimated 15 BBLs. The lateral valve was shut in immediately upon detection. Vacuum truck recovered an estimated 15 BBLs. The affected area will be water washed and soil samples will be taken. Failure was due to internal corrosion of 3 inch lined piping.

Describe measures taken to prevent the problem(s) from reoccurring:

Piping was replaced.

Volume of Soil Excavated (cubic yards): _____

Disposition of Excavated Soil (attach documentation) ☐ Offsite Disposal ☐ Onsite Treatment
☐ Other (specify) _____

Volume of Impacted Ground Water Removed (bbls): _____

Volume of Impacted Surface Water Removed (bbls): _____

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☒ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

This area noted on the Form 19 was walked and soil was probed with a shovel to identify any notable impacts and assure that representative samples were collected initially on 6/1/2015. No hydrocarbon odors were observed. Minor salt staining was observed. The SS1, SS3, SS4 and SS5 sample locations was re-sampled on 7/13/18 for SAR and EC (SS1, SS3, SS4 and SS5) and arsenic (SS1). The SS1 sample location was resampled for EC on 4/1/21 and the SS2 and SS4 locations were resampled for SAR and EC on 4/1/21. All samples are now within the COGCC Table 910-1 allowable concentrations. Chevron is requesting closure of Spill Release Point 440659 under Table 910-1 due to the initial release occurring during Table 910-1 rule. Samples were collected prior to the Table 915 adoption.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Chris Patterson

Title: Lead ENV Specialist Date: 04/11/2021 Email: spwu@chevron.com

Condition of Approval

COA Type

Description

	Based on review of information presented it appears that no further action is necessary at this time, and COGCC approves the closure request. However, should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if ground water is found to be impacted, then further investigation and/or remediation activities may be required at the site
1 COA	

Attachment List

Att Doc Num

Name

402654582	SPILL/RELEASE REPORT(SUPPLEMENTAL)
402654583	ANALYTICAL RESULTS
402661503	FORM 19 SUBMITTED

Total Attach: 3 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)